



Load Test Report

Customer:		kW Rating:	112	Date:	11/17/2021
Address:	5123 Hiltonview Rd. Houston, TX 77086	Model:	HRJW145	Technician:	Brandon Reynolds
Contact:		Serial Number:	U11400493	Job/Item #:	2587

[illegible]

COMMENTS: 15 Minutes @ 50% Load; 15 Minutes @ 75% Load; 30 Minutes @ 100% Load

If load requirements are not achievable due to load bank steps, load unit as close to the load requirement as possible. Record in notes section below.